

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-011517**Date Inspected:** 11-Jan-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li yan hua**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, S.Chandrakumar was present during the times noted above for observations relative to the work being performed.

OUTSIDE SHOP

FCAW welding of weld joint 3G-181 located on PCMK SSD11A-PP81 of 9EW welder is identified as 207465. ZPMC QC is identified as Mr.Li ping . The welding variables recorded by QC appeared to Comply with the WPS-B-T-2233-TC-U4b-F.

FCAW welding of weld joint 2G-226 located on PCMK SSD10-PP80 of 9DW welder is identified as 045246. ZPMC QC is identified as Mr. Li ping. The welding variables recorded by QC appeared to Comply with the WPS-B-T-2232-TC-U4b-F-1.

SMAW welding of weld joint 4F-174 located on PCMK SEG056D of 9DE welder is identified as 044772.ZPMC QC is identified as Mr. wang wei ming. The welding variables recorded by QC appeared to Comply with the WPS-B-P-2114-FCM-1.

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA inspector generated an MT report for this date. The members are identified as Segment 8CW. The weld designations reviewed are as follows: PP70.

DP94-001-088,093,098,101,106,109,099,104,112.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

DP121-001-115,120,125,128,133,136,141,144,126,134,147.
DP121-002-115,120,125,128,136,144,141,131,123,147.
DP148-001-100,105,113,118,121,126,129,134,137,111,119,130,140.
DP283-001-088,093,101,106,109.
DP175-001-100,105,110,113,118,121,126,129,134,137,119,124,140,132.
DP229-001-142,147,155,163,179,153,166,182,145.
DP256-001-142,147,152,155,163,168,171,176,179,153,169,177,182,180.
DP536-001-142,147,152,155,160,163,171,168,176,179,156,172,150,182.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang-15--0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Chadra	Quality Assurance Inspector
Reviewed By:	Patterson,Rodney	QA Reviewer
